






26 May 2020



With the onset of the rainy season in Nigeria's conflict-affected northeastern State of Borno, varying degrees of damages are expected to infrastructures (self-made and constructed) in camps and camp-like settings. This is so because the rains are more often than not accompanied by very high winds and have been known to cause serious damage to properties.

On 26 May 2020, IOM's DTM program carried out an assessment to ascertain the level of damage sustained in camps and camp-like settings due to heavy windstorm and rainfall between 23rd and 25th May 2020. Overall, 18 camps were affected in Gwoza, Bama, Maiduguri, Jere and konduga LGAs. The worst-hit of the camps assessed was the Muna EI-Badawy Camp in Jere Lga where a heavy windstorm reignited unguarded cooking fires. This led to a fire outbreak that left 622 makeshift shelters damaged and an estimated 3,576 individuals without shelter, with two casualties recorded in the disaster.



Other affected camps are: GSS Camp, Reception/Transit, Umbazah Rock Side, Wege Arrival Centre in Gwoza LGA; Bakasi Camp, Stadium Camp, Teachers Village, NYSC Camp, Musune, Suleimanti, Kaduwa I, Dogon Iche, Borgozo Camp, Shuwari 5 Camp in Maiduguri Metropolitan Council (MMC); Farm Centre in Jere LGA and 250 Housing Estate (Dalori II) in Konduga LGA.

Major complaints in the assessed camps are lack of shelter repair kits for reinforcement and blockage of drainage system restricting proper flow of water. Although the Camp Coordination and Camp Management (CCCM) unit of IOM have responded with the provision of over 100 sand bags, there is still a major need of shelter, shelter repair kits, construction and cleaning of drainages as a preparedness measure in all camps.

Damages at IDP Sites between 23rd and 25th May 2020

		Number of	Number of	Number of	Number of	Number of
Site Name	LGA	Damaged	Damaged	Damaged	Affected	Affected
		Shelters	Toilets	Shower Points	Households	Individuals
GSS CAMP	GWOZA	18	10	-	3	8
RECEPTION/TRANSIT	GWOZA	6	5	-	36	84
CAMP A (UMBAZAH ROCK SIDE)	GWOZA	46	-	-	46	206
CAMP D (WEGE ARRIVAL CENTRE)	GWOZA	124	-	-	124	472
TOTAL GWOZA		194	15	-	209	770
BANKI CAMP	BAMA	2	-	-	23	68
TOTAL BAMA		2	-	-	23	68
BAKASI CAMP	MAIDUGURI	17	10	-	17	71
STADIUM CAMP	MAIDUGURI	6	-	-	6	19
TEACHERS VILLAGE	MAIDUGURI	1	-	5	1	5
NYSC CAMP	MAIDUGURI	53	14	-	53	240
MUSUNE	MAIDUGURI	1	-	-	1	10
SULEIMANTI	MAIDUGURI	2	4	-	2	16
KADUWA I	MAIDUGURI	2	-	-	3	31
DOGON ICHE	MAIDUGURI	4	-	-	4	21
BORGOZO CAMP	MAIDUGURI	26	-	-	26	142
SHUWARI 5 CAMP	MAIDUGURI	1	-	-	1	6
TOTAL MAIDUGURI		113	28	5	114	561
FARM CENTRE	JERE	86	-	-	86	593
MUNA EL-BADAWY	JERE	622	5	-	622	3576
TOTAL JERE		735	5	-	708	4169
250 HOUSING ESTATE (DALORI II)	KONDUGA	1	-	-	2	7
TOTAL KONDUGA		1	-	-	2	7
TOTAL DAMAGES			48	5	1056	5575
	GSS CAMP RECEPTION/TRANSIT CAMP A (UMBAZAH ROCK SIDE) CAMP D (WEGE ARRIVAL CENTRE) TOTAL GWOZA BANKI CAMP TOTAL BAMA BAKASI CAMP STADIUM CAMP TEACHERS VILLAGE NYSC CAMP MUSUNE SULEIMANTI KADUWA I DOGON ICHE BORGOZO CAMP SHUWARI 5 CAMP TOTAL MAIDUGURI FARM CENTRE MUNA EL-BADAWY TOTAL JERE 250 HOUSING ESTATE (DALORI II)	GSS CAMPGWOZARECEPTION/TRANSITGWOZACAMP A (UMBAZAH ROCK SIDE)GWOZACAMP D (WEGE ARRIVAL CENTRE)GWOZATOTAL GWOZATOTAL GWOZATOTAL GWOZABANKI CAMPBANKI CAMPBANKI CAMPBANKASI CAMPMAIDUGURISTADIUM CAMPMAIDUGURITEACHERS VILLAGEMAIDUGURINYSC CAMPMAIDUGURIMUSUNEMAIDUGURISULEIMANTIMAIDUGURISULEIMANTIMAIDUGURIBORGOZO CAMPMAIDUGURIBORGOZO CAMPMAIDUGURISHUWARI 5 CAMPMAIDUGURITOTAL MAIDUGURIBORGOZO CAMPMAIDUGURIBORGOZO CAMPMAIDUGURIBORGOZO CAMPMAIDUGURISHUWARI 5 CAMPJEREMUNA EL-BADAWYJERE250 HOUSING ESTATE (DALORI II)KONDUGATOTAL KONDUGA	Site NameLGADamaged SheltersGSS CAMPGWOZA18RECEPTION/TRANSITGWOZA6CAMP A (UMBAZAH ROCK SIDE)GWOZA46CAMP A (UMBAZAH ROCK SIDE)GWOZA124TOTAL GWOZAGWOZA124TOTAL GWOZA124BANKI CAMPBAMA2BAKASI CAMPMAIDUGURI17STADIUM CAMPMAIDUGURI6TEACHERS VILLAGEMAIDUGURI53MUSUNEMAIDUGURI11SULEIMANTIMAIDUGURI2KADUWA IMAIDUGURI2BORGOZO CAMPMAIDUGURI26SHUWARI 5 CAMPMAIDUGURI1SULEIMANTIMAIDUGURI2SULEIMANTIMAIDUGURI26SHUWARI 5 CAMPMAIDUGURI1TOTAL MAIDUGURI11FARM CENTREJERE86MUNA EL-BADAWYJERE622TOTAL JERE735250 HOUSING ESTATE (DALORI II)KONDUGA1	Site NameLGADamaged SheltersDamaged ToiletsGSS CAMPGWOZA1810RECEPTION/TRANSITGWOZA65CAMP A (UMBAZAH ROCK SIDE)GWOZA46-CAMP D (WEGE ARRIVAL CENTRE)GWOZA124-GWOZA124TOTAL GWOZA94BANKI CAMPBAMA2-BANKI CAMPMAIDUGURI1710STADIUM CAMPMAIDUGURI6-TEACHERS VILLAGEMAIDUGURI1-MYSC CAMPMAIDUGURI1-MYSC CAMPMAIDUGURI24MUSUNEMAIDUGURI2-SULEIMANTIMAIDUGURI2-DOGON ICHEMAIDUGURI26-SHUWARI S CAMPMAIDUGURI1-DOGON ICHEMAIDUGURI26-SHUWARI S CAMPMAIDUGURI1-DOGON ICHEMAIDUGURI26-SHUWARI S CAMPMAIDUGURI1-TOTAL MAIDUGURIJERE86-FARM CENTREJERE86-MUNA EL-BADAWYJERE6225TOTAL JERE7355250 HOUSING ESTATE (DALORI II)KONDUGA1TOTAL KONDUGA1-TOTAL KONDUGA1-	Site NameLGADamaged SheltersDamaged ToiletsDamaged Shower PointsGSS CAMPGWOZA1810-RECEPTION/TRANSITGWOZA65-CAMP A (UMBAZAH ROCK SIDE)GWOZA46CAMP D (WEGE ARRIVAL CENTRE)GWOZA46CAMP D (WEGE ARRIVAL CENTRE)GWOZA124TOTAL GWOZA19415BANKI CAMPBAMA2BANKI CAMPMAIDUGURI1710-BAKASI CAMPMAIDUGURI6TEACHERS VILLAGEMAIDUGURI6NYSC CAMPMAIDUGURI1-5NYSC CAMPMAIDUGURI1MUSUNEMAIDUGURI24-MUSUNEMAIDUGURI2DOGON ICHEMAIDUGURI26BORGOZO CAMPMAIDUGURI1SHUWARI S CAMPMAIDUGURI26SHUWARI S CAMPMAIDUGURI1FARM CENTREJERE86GUOSO CAMPJERE6225-TOTAL BADWYJERE6225-TOTAL LORNINKONDUGA1TOTAL LORNINKONDUGA1	Site NameLGADamaged SheltersDamaged ToiletsDamaged Shower PointsAffected HouseholdsGSS CAMPGWOZA1810-3RECEPTION/TRANSITGWOZA65-36CAMP A (UMBAZAH ROCK SIDE)GWOZA4646CAMP D (WEGE ARRIVAL CENTRE)GWOZA46124TOTAL GWOZAGWOZA124124TOTAL GWOZABAMA223BANKI CAMPBAMA223TOTAL BAMA223BAKASI CAMPMAIDUGURI17100-17STADIUM CAMPMAIDUGURI17100176TEACHERS VILLAGEMAIDUGURI1-51MUSUNEMAIDUGURI1314-3MUSUNEMAIDUGURI11SULEIMANTIMAIDUGURI23MUSUNEMAIDUGURI21SULEIMANTIMAIDUGURI23DOGON ICHEMAIDUGURI126SHUWARI SCAMPMAIDUGURI11TOTAL MAIDUGURI113MUNA EL-BADAWYJERE861FARM CENTREJERE86622SUNWARI SCAMPJERE85-

DATA SOURCE: IOM-DTM RAPID ASSESSMENT TEAM

The maps in this report are for illustration purposes only. The depiction and use of boundaries, geographic names, and related data shown on maps and included in this report are not warranted to be error free nor do they imply judgment on the legal status of any territory, or any endorsement or acceptance of such boundaries by IOM



