

Monguno, Bama and Gwoza LGAs (Local Government Areas)

SUMMARY



200 Households



671 Individuals




3 sites



130 Damaged shelters



11 Damaged toilets




8 Damaged shower points

With the onset of the rainy season in Nigeria's conflict-affected northeastern state of Borno, varying degrees of damages are expected to infrastructures (self-made and constructed) in camps and camp-like settings. Usually, heavy rainfalls are accompanied by strong winds causing serious damage to shelters of IDPs.

Between 17 and 23 June 2021, IOM's DTM programme carried out assessments to ascertain the level of damage sustained in camps and camp-like settings due to heavy windstorms and rainfall. Overall, 2 camps and 1 collective settlement in the LGAs Monguno, Bama and Gwoza LGAs were assessed. The worst-hit of the camps assessed was Government Girls Secondary School (GGSS) camp in Monguno LGA where a heavy rainfall damaged 33 shelters, affecting an estimated 431 individuals.

In total, 130 shelters were damaged by storms, leaving a total of 200 households without shelter. Additionally, a total of 11 toilets and 8 showers were damaged by storms. There was no casualty as a result of the storms.



The maps in this report are for illustration purposes only. The depiction and use of boundaries, geographic names, and related data shown on maps and included in this report are not warranted to be error free nor do they imply judgment on the legal status of any territory, or any endorsement or acceptance of such boundaries by IOM


There is a major need of shelter, shelter repair kits and WASH. As a preventive measure against flooding, most IDP sites need good drainage systems and the use of sand bags to channel the water flow.



Above are Pictures taken at the site showing damaged shelters and flooded areas.



Most Needed Assistance. FIG 1.1



Damages at IDP Sites

LGA	Ward	Site Type	Site Name	Number of Affected Household	Number of Affected Individuals	Male	Female	Number of Damaged Shelter	Number of Damaged Toilets	Number of Damaged Showers
Bama	Shehuri / Hausari / Mairi	Camp	GSSSS Camp	93	225	91	134	93	0	0
Gwoza	Hambagda/ Liman kara	Camp	20 Housing	4	15	8	7	4	0	0
Monguno	Monguno	Collective settlement	GGSS Camp	103	431	185	246	33	11	8
Grand Total				200	671	284	387	130	11	8

DATA SOURCE: IOM-DTM RAPID ASSESSMENT TEAM

"When quoting, paraphrasing, or in any other way using the information mentioned in this report, the source needs to be stated appropriately as follows: "Source: Displacement Tracking Matrix (DTM) of the International Organization for Migration (IOM), June 2021""



Henry Kwenin, DTM Project Coordinator | hkwenin@iom.int



Humanitarian Aid
And Civil Protection